

REVISED SUBMITAL 1 5/29/08 REVISED SUBMITAL EBH INITAL SUBMITAL EBH


SUTTER LAKESIDE HOSPITAL 5176 HILL ROAD EAST LAKEPORT CALIFORNIA 95453 SITE DETAIL SHEET

EXISTING SUTTER LAKESIDE HOSPITAL 5176 HILL ROAD EAST, LAKEPORT CA



RUZICK CON CIVIL ENGIN P.O. BOX LAKEPORT

CKA ASSOCIATES CONSULTING ENGINEERS GENERIC PLANNING SURVEYING BOX 1189 2495 PARALLEL DRIVE RT CA. 95453 (707) 263-6155 FAX (707) 263-0768	DRAWN BY: EBH	DATE: JUNE 10, 2008
	CHECKED BY: TAH RCE: 53327	DRAWING NO.: ROUNDABOU
	лов но.: 04—5667.02	SHEET C10 OF



2	6/10/08	REVISED SUBMITAL	EBH
1	5/29/08	REVISED SUBMITAL	EBH
0	5/19/08	INITAL SUBMITAL	EBH
NO.	DATE	DESCRIPTION	BY

SUTTER LAKESIDE HOSPITAL 5176 HILL ROAD EAST LAKEPORT CALIFORNIA 95453 LANDSCAPE RETAINING WALL DETAIL

EXISTING SUTTER LAKESIDE HOSPITAL

5176 HILL ROAD EAST, LAKEPORT CA



RUZICKA ASSOCIATES

CONSULTING ENGINEERS

CIVIL ENGINEERING PLANNING SURVEYING
P.O. BOX 1189 2495 PARALLEL DRIVE
LAKEPORT CA. 9453 (707) 263-6155
FAX (707) 263-0768

DRAWN BY: EBH	DATE: JUNE 10, 2008
CHECKED BY: TAH RCE: 53327	DRAWING NO.: ROUNDABOUT
лов NO.: 04—5667.02	SHEET C11 OF